# **Energy performance certificate** (EPC)

6 Mayfield Avenue Dromara DROMORE BT25 2NP	Energy rating	Valid until:	15 March 2033
		Certificate number:	2090-5727-1170-0709-5891

# **Property type**

**Detached house** 


## **Total floor area**

319 square metres

## **Energy efficiency rating for this property**

This property's current energy rating is C. It has the potential to be C.

See how to improve this property's energy performance.



The graph shows this property's current and potential energy rating.

Properties get a rating from A (best) to G (worst) and a score. The better the rating and score, the lower your energy bills are likely to be.

For properties in Northern Ireland:

- the average energy rating is D
- the average energy score is 60

#### Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- very good (most efficient)
- good
- average
- poor
- · very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

Feature	Description	Rating
Wall	Cavity wall, as built, insulated (assumed)	Good
Roof	Pitched, 200 mm loft insulation	Good
Roof	Roof room(s), insulated (assumed)	Good
Window	Fully double glazed	Good
Main heating	Boiler and underfloor heating, oil	Average
Main heating control	Time and temperature zone control	Very good
Hot water	From main system	Average
Lighting	Low energy lighting in 79% of fixed outlets	Very good
Floor	Solid, insulated (assumed)	N/A
Secondary heating	Room heaters, wood logs	N/A

# Low and zero carbon energy sources

Low and zero carbon energy sources release very little or no CO2. Installing these sources may help reduce energy bills as well as cutting carbon emissions. The following low or zero carbon energy sources are installed in this property:

· Biomass secondary heating

# Primary energy use

The primary energy use for this property per year is 108 kilowatt hours per square metre (kWh/m2).

What is primary energy use?

## **Environmental impact of this property**

This property's current environmental impact rating is C. It has the potential to be C.

Properties get a rating from A (best) to G (worst) on how much carbon dioxide (CO2) they produce each year. CO2 harms the environment.

# An average household produces

6 tonnes of CO2

## This property produces

8.0 tonnes of CO2

# This property's potential production

8.0 tonnes of CO2

You could improve this property's CO2 emissions by making the suggested changes. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

#### Improve this property's energy rating

Follow these steps to improve the energy rating and score.

▶ <u>Do I need to follow these steps in order?</u>

# Step 1: Solar water heating

## Typical installation cost

£4,000 - £6,000

## Typical yearly saving

£98

## Potential rating after completing step 1

76 | C

# Step 2: Solar photovoltaic panels, 2.5 kWp

# Typical installation cost

£3,500 - £5,500

# Typical yearly saving

£625

# Potential rating after completing steps 1 and 2

80 | C

# Paying for energy improvements

You might be able to get a grant from the <u>Boiler Upgrade Scheme (https://www.gov.uk/apply-boiler-upgrade-scheme)</u>. This will help you buy a more efficient, low carbon heating system for this property.

#### Estimated energy use and potential savings

Based on average energy costs when this EPC was created:

# Estimated yearly energy cost for this property

£2977

# Potential saving if you complete every step in order

The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

# Heating use in this property

Heating a property usually makes up the majority of energy costs.

## Potential energy savings by installing insulation

The assessor did not find any opportunities to save energy by installing insulation in this property.

#### Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

## Assessor contact details

## Assessor's name

Ciaran Stuart

## **Telephone**

07764612066

#### **Email**

info@spsni.com

# Accreditation scheme contact details

## **Accreditation scheme**

**Quidos Limited** 

#### Assessor ID

QUID208899

# **Telephone**

01225 667 570

## **Email**

info@quidos.co.uk

# **Assessment details**

# Assessor's declaration

No related party

## Date of assessment

15 March 2023

## **Date of certificate**

16 March 2023

# Type of assessment



► RdSAP

## Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <u>dluhc.digital-services@levellingup.gov.uk</u> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related certificates for this property.